




Structurally Deficient Bridges on the National Highway System Virginia - Congressional District 05



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 112 structurally deficient NHS bridges in Virginia, 8 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	10059	220 NBL & 57 WBL	5.85 Frk Co; 7.78 Rt 58
2	10063	Virginia Ave. 220	0.42 Rt 220BP; 3.88 Martv
3	20638	ROUTE 0058	0057CHURCH ST0043220
4	13423	SBL Route 0029	0.05-RT.803/1.37-RT29 BUS
5	1339	NBL Route 29	.00 Amher /.00 Nelson
6	12401	SBL ROUTE 0029	0.90-Rt.741/0.40-Rt.653
7	11885	EBL HWY FIFTYEIGHT	.23 FR 732 & .27 TO 735
8	497	ROUTE 64	6.85 FR 250&3.73 TO 29
9	20096	ROUTE 0250	0001RUGBY RD 0002MCINTR R
10	20087	ROUTE 0020	0.10GARRET ST/0.14 TO 250
11	11915	SBL ROUTE 0085	3.2 FR 903 & 4.9 TO 58