




Structurally Deficient Bridges on the National Highway System



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2005, all data is from the 2007 NBI. Of the 89 structurally deficient NHS bridges in Washington, 13 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	0006926C0000000	BIRCH BAY-LYNDEN R	4.3 N JCT SR 548
2	803100000000000	SLATER RD	02.43 W OF NW DR
3	832160000000000	MARINE DR	0.3 S BENNETT DR.
4	855260000000000	CHESTNUT ST-BAY ST	.25 W FED BLDG
5	000000FJ0000000	STATE ROUTE 529	1.4 N JCT SR 5
6	0001652A0000000	I-5	0.7 N JCT SR 530
7	0007651B0000000	US 2	2.1 E JCT I-5
8	8378	US 2	0.8 E JCT I-5