




Structurally Deficient Bridges on the National Highway System Washington - Congressional District 04



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



- Deficient Bridges
- City
- Interstate Highway
- Other NHS Highway
- Body of Water
- Urbanized Areas
- 10th Congressional District



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 89 structurally deficient NHS bridges in Washington, 13 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	0006883B00000000	I-90	21.6 E KING CO
2	0009428A00000000	I-90	22.9 E KING CO
3	0007016A00000000	I-90	22.9 E KING CO
4	0000267A00000000	I-90	26.3 E KING CO
5	0003527A00000000	I-90	28.2 E KING CO
6	0001686A00000000	US 12	25.5 E LEWIS CO
7	0001686B00000000	US 12	26.0 E LEWIS CO
8	0006539A00000000	US 97	OREGON LINE
9	0002001A00000000	US 2	4.7 E JCT SR 207
10	0007724A00000000	I-90	11.4 E JCT SR 970
11	0006113A00000000	US 97	18.6 N JCT SR 142
12	0008036C00000000	I-90	18.9 E JCT SR 970
13	8458600000000000	40TH AVE.,S.	00.09 SO LOGAN AVE
14	8548900000000000	NOB HILL BLVD	00.02 W SO 1ST ST
15	0008672B00000000	I-82	3.2 E JCT I-90
16	0002689B00000000	US 97	12.3 N KLINKITAT CO
17	8273100000000000	YAKIMA AVE., E.	00.04 E OF N18TH ST
18	0001942A00000000	SR 22	1.0 E JCT I-82
19	0010534A00000000	WINE COUNTRY RD	6.9 E YAKIMA CO LN