




Structurally Deficient Bridges on the National Highway System Washington - Congressional District 05



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 89 structurally deficient NHS bridges in Washington, 13 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	83991000000000	LOWDEN GARDENA RD	02.66E FROG HOLLOW
2	0005761A00000000	I-90	1.5 E JCT US 395
3	0005761B00000000	I-90	1.5 E JCT US 395
4	0010320A00000000	SR 26	1.1 E JCT SR 261
5	000000GL00000000	US 12	21.1 E JCT 125
6	0000307A00000000	US 12	13.0 E WALLA WAL CO
7	000000FE00000000	SR 290	0.9 E JCT US 2
8	0005453A00000000	I-90	1.7 E JCT US 2
9	5453	I-90	3.0 E JCT US 2
10	80598000000000	BARKER ROAD	0.5 S EUCLID ROAD
11	0010850A00000000	SR 193	0.2 E JCT US 12
12	0002348A00000000	US 12	0.1 E JCT SR 129