




Structurally Deficient Bridges on the National Highway System



Consult your state DOT for the most up-to-date status of bridges.



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2005, all data is from the 2007 NBI. Of the 89 structurally deficient NHS bridges in Washington, 13 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	0008100G00000000	I-5	2.2 N JCT SR 510
2	0002069A00000000	I-5	0.1 N THURSTON CO
3	0005394A00000000	FT LEWIS-DUPONT	4.3 N THURSTON CO
4	0006069A00000000	STATE ROUTE 509	2.5 N JCT I-5
5	0014409B00000000	SR 509	0.7 N JCT I-705
6	8501100000000000	PUYALLUP AVENUE	0.2 N JCT I-5
7	0003960A00000000	SR 167	0.2 S JCT SR 161
8	0007401A00000000	S178TH ST	4.0 N JCT SR 516